





1 Choose the Model



2 Choose the Test Beds



3 Choose the Sample Clamp Frames



4 Choose the Tool Holders

ONLY WITH AB5045 One wide track
2 POSSIBLE WITH 2 SAMPLE CLAMP FRAMES



ONLY WITH AB5197 Two narrow tracks
2 POSSIBLE WITH 2 SAMPLE CLAMP FRAMES



5 Choose the Tools

ONLY WITH AB5042
2 POSSIBLE WITH 2 TOOL HOLDERS

- Sponge with holder
AB5012
AB5019
- Wild boar brush
AB5010
AB5017
- Nylon brush
AB5011
AB5018
- Abrasive pad tool
AB5013
AB5016
- Universal clamp
AB5020
- MEK/Crockmeter
AB5058
AB5059
AB5060
AB5056

ONLY WITH AB5043
2 POSSIBLE WITH 2 TOOL HOLDERS

- Large sponge with holder
AB5050
AB5051
AB5057

ONLY WITH AB5041
4 POSSIBLE WITH 2 TOOL HOLDERS

- Sponge with holder
AB5012
AB5019
- Wild boar brush
AB5010
AB5017
- Nylon brush
AB5011
AB5018
- Abrasive pad tool
AB5013
AB5016
- Universal clamp
AB5020
- MEK/Crockmeter
AB5058
AB5059
AB5060
AB5056

ONLY WITH AB5044
4 POSSIBLE WITH 2 TOOL HOLDERS

- Cloth holder
AB5055

ONLY WITH AB5041
4 POSSIBLE WITH 2 TOOL HOLDERS

- Sponge with holder
AB5012
AB5019
- Wild boar brush
AB5010
AB5017
- Nylon brush
AB5011
AB5018
- Abrasive pad tool
AB5013
AB5016
- Universal clamp
AB5020
- MEK/Crockmeter
AB5058
AB5059
AB5060
AB5056

ONLY WITH AB5044
4 POSSIBLE WITH 2 TOOL HOLDERS

- Cloth holder
AB5055

6 Choose the Accessories

WEIGHTS

